

L Number	Hits	Search Text	DB	Time stamp
1	291137	mask or photomask or reticle	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:02
2	439960	stress or stresses or stressed	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:03
3	428351	laser	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:03
4	2102808	heat or heating or heated	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:04
5	8009	((stress or stresses or stressed ) same laser	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:04
6	5188	((heat or heating or heated) and ((stress or stresses or stressed ) same laser)	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:06
7	753931	shift or shifting or shifted or shifter	USPAT; US-PGPUB; EPO; JPO	2003/06/16 11:06
9	871	((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)	USPAT	2003/06/16 11:08
10	28910	((stress or stresses or stressed ) with (heat or heating or heated)	USPAT	2003/06/16 11:08
11	239	((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))	USPAT	2003/06/16 11:08
12	4226	430/5	USPAT	2003/06/16 11:08
13	9	((((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 430/5	USPAT	2003/06/16 11:12
14	212612	laser not (((((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 430/5)	USPAT	2003/06/16 11:12
15	9	laser not (laser not (((((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 430/5))	USPAT	2003/06/16 11:35
16	308000	4.clm.	USPAT	2003/06/16 11:35
17	116	((((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 4.clm.	USPAT	2003/06/16 11:36
18	261	((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and 4.clm.	USPAT	2003/06/16 11:37
19	8	430/5 and (((((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and 4.clm.)	USPAT	2003/06/16 11:37

20	4	(430/5 and (((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and 4.clm.)) not (((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 430/5)	USPAT	2003/06/16 11:46
21	38426	1.clm.	USPAT	2003/06/16 11:46
22	3874	1.clm. and 4.clm.	USPAT	2003/06/16 11:46
23	40	(1.clm. and 4.clm.) and ((heat or heating or heated) and ((stress or stresses or stressed ) same laser))	USPAT	2003/06/16 11:46
24	37	((1.clm. and 4.clm.) and ((heat or heating or heated) and ((stress or stresses or stressed ) same laser))) not (laser not (laser not (((heat or heating or heated) and ((stress or stresses or stressed ) same laser)) and (shift or shifting or shifted or shifter)) and ((stress or stresses or stressed ) with (heat or heating or heated))) and 430/5)))	USPAT	2003/06/16 11:47